


- This is a latching isolator to give the strongest connection when under load over rough ground.
- To activate this ON & OFF you will need a 2 way switch that changes the polarity on the spade terminals:





Wiring Diagram